Advanced Blockage Clearance Ltd

84 Upper Ratton Drive EASTBOURNE BN20 9DJ

Mobile: 07866 410870Telephone: 01323 503345 E - Mail: .Ross@abcdrainage.co.uk

CCTV DRAINAGE REPORT

Client: Artemis Build

Location: Ashwood Nursing Home Heathfield Road Burwash Common

Date: 16th February 2021

Order no: Email Nick

Manhole 1

Green dye can be seen in this run from rain water drain

0.00m Survey starts downstream

2.60m Pipework heavily cracked/broken

3.50m Pipework heavily dis-jointed

7.30m Enters Manhole in road (Southern Water Manhole)

This is last Manhole on site before leaving site Manhole Photo Below



Advanced Blockage Clearance Ltd

84 Upper Ratton Drive EASTBOURNE BN20 9DJ

Mobile: 07866 410870Telephone: 01323 503345 E - Mail: .Ross@abcdrainage.co.uk

Manhole 1

Green dye can be seen in this run from rain water drain

0.00m Survey starts upstream

27.10m Enters Manhole 2

Green dye flowing through Manhole from Rain Water shown in

Photo Below.



Advanced Blockage Clearance Ltd

84 Upper Ratton Drive EASTBOURNE BN20 9DJ

Mobile: 07866 410870Telephone: 01323 503345 E - Mail: .Ross@abcdrainage.co.uk



In Photo Above this is Manhole 2 showing the green tracing dye which was used in the Rain water gulley flowing into the foul system.